NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION Office of Vehicle Safety Compliance COMPLIANCE STATUS REPORT REPORT DATE: July 15, 2007

The following definitions are essential to the interpretation of the report:

INVESTIGATIONS —

CT (Compliance Test) — Investigations initiated based on the results of scheduled compliance test programs.

CI Number — OVSC Compliance Investigation Number (such as "CI-208-020320")

The CI number identifies FMVSS 208 with a test failure date of March 20, 2002. A compliance investigation is established when there is a <u>reasonable expectation</u> that a noncompliance may exist.

PE Number — OVSC Preliminary Evaluation Number (such as "PE-214-020320")

The PE number identifies FMVSS 214 with a test failure date, inspection date, complaint date, etc., of March 20, 2002. A preliminary evaluation action is taken to gather additional information in cases where there is only a <u>possibility</u> of a noncompliance.

The following types of investigations initiated as a result of information obtained from sources other than scheduled compliance test programs such as consumer complaints, industry disclosures, articles in the news media, etc:

IN (Inspection) CP (Complaint) MD (Manufacturer Defect)

ID (Part 574) MI (Manufacturer Inquiry)

COMPLIANCE TESTING —

TEST PROGRAM — Tests conducted in accordance with scheduled compliance test programs

RETEST — Retesting of items that have initially failed during a scheduled compliance test program

RESPONSIVE — Not a part of a scheduled compliance test program but consists of special testing, consumer complaint testing, etc.

COMPLIANCE TESTING LEGEND —

The following identifiers are used:

STD - Federal Motor Vehicle Safety Standard (FMVSS) or Regulation (i.e., Part 575, Part 567)

LAB - Testing laboratory under contract to OVSC

GRP - Test report group number. The following identifiers are found in the last character of the GRP number for those tests other than SCHEDULED compliance tests: R – Retest, T - Response test

SPECIAL CASES: FMVSS 109 - S=Test Program, R=Retest, C=Responsive FMVSS 119 - A=Test Program, B=Retest, C=Responsive

US MFR/US DISTRIBUTOR - Manufacturer or distributor of motor vehicle or equipment item

MAKE - Make of motor vehicle or equipment item

MODEL - Information for motor vehicle or equipment item

 $\textbf{STYLE/COMPONENT} \ - \ Information \ for \ motor \ vehicle \ or \ equipment \ item$

IDENTIFICATION NUMBER - Tire identification number

MY - Motor vehicle model year

HS NO. - Test report number used by the NHTSA Technical Information Services for identification purposes

RESULT - Test results (PASS or FAIL)

FAIL - P: performance failure FAIL - I: inspection failure

FAIL - L: labeling or instruction failure

REPORTS ACCEPTED DURING JUNE 2007 FOR FY 2007 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.

	LAB/	MFR/	MY/MAKE/	RESULT/
STD	GRP	DISTRIB	MODEL/STYLE	HS NO.
108	CAN	NISSAN	2006 STANLEY	FAIL-P ¹
	001		NISSAN ALTIMA LAMPS CONSPICULTY SYS.	638871
108	CAN	MAXZONE	2004 DEPO	FAIL-P ²
	002		NISSAN ALTIMA LAMPS CONSPICULTY SYS.	638872
108	CAN	ANZO USA	2004 EAGLE EYES	FAIL-P ³
	003		NISSAN ALTIMA LAMPS CONSPICULTY SYS.	638904
110	MGA	CORBEIL	2006 CORBEIL	FAIL-L ⁴
	001	INTERNATIONAL	SW5 SCHOOL BUS	638918
120	MGA	THOMAS BUILT	2007 THOMAS	PASS
	002		C2 SCHOOL BUS	638919
135	TRC	NISSAN	2006 NISSAN	PASS
	005		SENTRA 4-DOOR SEDAN	638851
135	TRC	GMC	2007 CHEVROLET	PASS
	006		TAHOE MPV 4-DOOR	638917
206	MGA	GMC	2007 CHEVROLET	PASS
	010		TAHOE DOOR LATCH/HINGE	638850
206	MGA	GMC	2007 SATURN	PASS
	013		VUE DOOR LATCH/HINGE	638849
206	MGA	GMC	2007 SATURN	PASS
	014		VUE DOOR LATCH/HINGE	638950
208	MGA	HYUNDAI	2007 HYUNDAI	PASS
	001		ELANTRA 4-DOOR SEDAN	638948
208	MGA	MAZDA	2007 MAZDA	PASS
	002		CX-7 MPV 4-DOOR	638949
208	MGA	DAIMLER/	2006 DODGE	PASS
	016	CHRYSLER	RAM 1500 PICKUP TRUCK 2-DOOR	638947
209	DTB	DAIMLER/	2007 DODGE	PASS
	002	CHRYSLER	RAM 1500 SEAT BELT ASSY.	638852
209	DTB	GMC	2007 BUICK	PASS
	006		LUCERNE SEAT BELT ASSY.	638853
209	DTB	GMC	2007 CADILLAC	PASS
	007		CTS SEAT BELT ASSY.	638854
209	DTB	GMC	2007 CHEVROLET	PASS
	008		SILVERADO SEAT BELT ASSY.	638855
209	DTB	GMC	2007 HUMMER	PASS
	009		H3 SEAT BELT ASSY.	638856
209	DTB	GMC	2007 CHEVROLET	PASS
	012	- · · · · ·	MALIBU SEAT BELT ASSY.	638857
209	DTB	GMC	2007 PONTIAC	PASS
	013	- · · · · ·	G6 SEAT BELT ASSY.	638858

¹ Halogen Headlamps-Photometric Test, under review ² Halogen Headlamps-Photometric Test, under review ³ Halogen Headlamps-Photometric Test, under review ⁴ Labeling failure, under review

REPORTS ACCEPTED DURING JUNE 2007 FOR FY 2007 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.

	LAB/	MFR/	MY/MAKE/	RESULT/
STD	GRP	DISTRIB	MODEL/STYLE	HS NO.
209	DTB	GMC	2007 SATURN	PASS
200	014	CIVIO	AURA SEAT BELT ASSY,	638859
209	DTB	GMC	2007 SATURN	PASS
	015	00	VUE SEAT BELT ASSY.	638860
212	MGA	HYUNDAI	2007 HYUNDAI	PASS
	001	-	ELANTRA 4-DOOR SEDAN	638948
212	MGA	MAZDA	2007 MAZDA	PASS
	002		CX-7 MPV 4-DOOR	638949
212	MGA	DAIMLER/	2006 DODGE	PASS
	016	CHRYSLER	RAM 1500 PICKUP TRUCK 2-DOOR	638947
213	UST	COMBI	2007 COMBI	PASS
	013		CONNECTION INFANT CHILD RESTRAINT	638863
213	UST	COMBI	2007 COMBI	PASS
	014		CENTRE DX INFANT CHILD RESTRAINT	638862
213	UST	EVENFLO	2007 EVENFLO	PASS
	033		FIRST CHOICE INFANT CHILD RESTRAINT	638865
213	UST	EVENFLO	2007 EVENFLO	PASS
	034		DISCOVERY INFANT CHILD RESTRAINT	638866
213	UST	EVENFLO	2007 EVENFLO	PASS
0.10	035	E) (E) IEI O	EMBRACE INFANT CHILD RESTRAINT	638867
213	UST	EVENFLO	2007 EVENFLO	PASS
040	036	EVENELO	TITAN 5 CONV. CHILD RESTRAINT	638868
213	UST	EVENFLO	2007 EVENFLO	PASS
213	037 UST	EVENFLO	TRIUMPH 5 PREMIER CONV. CHILD RESTRAINT 2007 EVENFLO	638869 PASS
213	038	EVENTLO	TRIBUTE CONV. CHILD RESTRAINT	638870
213	UST	EVENFLO	2007 EVENFLO	PASS
213	039	LVLINI LO	TRIBUTE 5 CONV. CHILD RESTRAINT	638884
213	UST	EVENFLO	2007 EVENFLO	PASS
210	040	LVLINILO	CHASE COMB. CHILD RESTRAINT	638885
213	UST	EVENFLO	2007 EVENFLO	PASS
	041	2.72.11.20	EXPRESS COMB. CHILD RESTRAINT	638886
213	UST	EVENFLO	2007 EVENFLO	PASS
	042		TRADITIONS COMB. CHILD RESTRAINT	638887
213	UST	EVENFLO	2007 EVENFLO	PASS
	043		GENERATIONS COMB. CHILD RESTRAINT	638888
213	UST	EVENFLO	2007 EVENFLO	PASS
	044		BOLERO COMB. CHILD RESTRAINT	638889
213	UST	GRACO	2007 GRACO	PASS
	049		SAFESEAT STEP 1 INFANT CHILD RESTRAINT	638907
213	UST	GRACO	2007 GRACO	PASS
	050		COMFORTSPORT CONV. CHILD RESTRAINT	638908
213	UST	GRACO	2007 GRACO	PASS
	051		SAFESEAT STEP 2 TODDLER CHILD RESTRAINT	638909

REPORTS ACCEPTED DURING JUNE 2007 FOR FY 2007 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.

	LAB/	MFR/	MY/MAKE/	RESULT/
STD	GRP	DISTRIB	MODEL/STYLE	HS NO.
213	UST	GRACO	2007 GRACO	PASS
	052		CARGO BOOSTER CHILD RESTRAINT	638910
213	UST	PEG PEREGO	2007 PEG PEREGO	PASS
	053		PRIMO VIAGGIO INFANT CHILD RESTRAINT	638912
213	UST	RECARO	2007 RECARO	PASS
	054		YOUNG SPORT CONV. CHILD RESTRAINT	638913
213	UST	IMMI SAFEGUARD	2007 SAFEGUARD	PASS
	055		SAFEGUARD TODDLER CHILD RESTRAINT	638911
213	UST	SUNSHINE KIDS	2007 SUNSHINE KIDS	PASS
	056		RADIAN 65 CONV. CHILD RESTRAINT	638914
213	UST	SUNSHINE KIDS	2007 SUNSHINE KIDS	PASS
	057		RADIAN 80 CONV. CHILD RESTRAINT	638915
213	UST	TRIPLE PLAY PRO	2007 TRIPLE PLAY	PASS
	058		PRO SIT'N STROLL CONV. CHILD RESTRAINT	638916
214	CAL	GMC	2007 BUICK	PASS
	800		LACROSSE 4-DOOR SEDAN	638861
218	UST	HM DISTRIBUTING	2007 EXL	FAIL-L ⁵
	003		662 COMP. FACIAL MOTORCYCLE HELMET	638845
218	UST	HM DISTRIBUTING	2007 EXL	PASS
	004		115 PARTIAL MOTORCYCLE HELMET	638846
218	UST	KIDO INDUSTRIAL	2007 SCORPION	PASS
	005		VX-14 COMP. FACIAL MOTORCYCLE HELMET	638844
218	UST	STRATEGIC SPORT	2007 ZAMP	PASS
	006		S-2 PARTIAL MOTORCYCLE HELMET	638847
218	UST	BELL HELMETS	2007 BELL	PASS
	007		DRIFTER PARTIAL MOTORCYCLE HELMET	638848
222	MGA	US BUS	2006 US BUS	FAIL-P ⁶
	005	MANUFACTURE	STURDIBUS SCHOOL BUS	638925
301	MGA	HYUNDAI	2007 HYUNDAI	PASS
	001		ELANTRA 4-DOOR SEDAN	638948
301	MGA	MAZDA	2007 MAZDA	PASS
	002		CX-7 MPV 4-DOOR	638949
301	MGA	DAIMLER/	2006 DODGE	PASS
	016	CHRYSLER	RAM 1500 PICKUP TRUCK 2-DOOR	638947

⁵ Labeling failure, under review ⁶ Bus seat rearward deflection failure and FMVSS 210/222 seat failure, under review

COMPLIANCE INVESTIGATIONS (CIs) IN PROGRESS THROUGH JUNE 2007 (CI NUMBER SYSTEM EXAMPLE: "CI-208-051220" FOR FMVSS 208 WITH A TEST FAILURE DATE OF DECEMBER 20, 2006)

NONE

CIS OPENED SINCE LAST REPORT

NONE

CIS CLOSED SINCE LAST REPORT

NONE

CAUSE:

PE Petition
CT Compliance Test
IN Inspection
CP Complaint
ID Part 574
MI Mfgr. Inquiry
MD Mfgr. Defect

PRELIMINARY EVALUATION INVESTIGATIONS (PEs) IN PROGRESS THROUGH JUNE 2007 (PE NUMBER SYSTEM EXAMPLE: "PE-208-051220" FOR FMVSS 208 WITH A TEST FAILURE DATE OF DECEMBER 20, 2006)

PE NO.	MFR/MY/MAKE/MODEL/FAILURE	CAUSE
PE-301-070328	Thomas Built Buses/2007 Thomas C2/Solv spill-30mph mov contour barr exc 1OZ/1min-next 25 min	CT
PE-222-070329	US Bus Manufacturing/2007 US Bus/Sturdibus/Under 10,000 pounds	СТ

PES OPENED SINCE LAST REPORT

NONE

PES CLOSED SINCE LAST REPORT

PE NO.	MFR/MY/MAKE/MODEL/FAILURE
PE-222-070222	Mid Bus Inc./2007 Mid Bus Guide DW/ Restraining barrier did not meet requirements/ Closed by NHTSA 5/18/2007

CAUSE:

PE Petition CT Compliance Test IN Inspection CP Complaint ID Part 574 MI Mfgr. Inquiry MD Mfgr. Defect